

# New Spec High Speed Wiring Diagram

A1/A2 - Auto Switch: Connect to on/off on new board.

P1/P2/P3 - Pot: Already wired to board.

M1/M2/M3 - Motor Plug

